## National Playground Safety Week





Guardrails or walls should be installed on all elevated surfaces.

April 22-26, 2024



Beware of spaces that may allow entrapment of limbs. Ladder rungs should be less than 3.5 inches or greater than 9 inches apart.



Damaged equipment should be removed or replaced. Inspect wooden equipment for splintering or cracks. Check metal equipment for rust.

There should be no protruding objects with sharp or unfinished edges, nor anything that could cut a child or catch their clothing.

Cushioned ground surfaces such as wood chips or shredded rubber reduce injuries and should extend at least 6' beyond the perimeter of all equipment.

You can visit Public Playground Safety—http://www.cpsc.gov— for more information. LARM provides playground inspections for its members. Contact James at james.kelley@larmpool.org or Fred at fred.wiebelhaus@larmpool.org to schedule an inspection.

Larmpool.org